

Items Available for Immediate Shipment

Photos Actual Size

Ford Tapping Screw, Moulding Clip & Retainer. Jeep & Fiat Moulding Retainer and Fiat Grommet. Infiniti & Nissan U-Nut.




25062
(Ford: W705392-S307)
Black Zinc

Hex Head Sems® Tapping Screw
M4.2-1.41 x 22mm
Washer Diameter: 13mm
Hex Size: 5.5mm
Fender Liner

Ford Explorer 2018 - 2013, F150 2009 - On, Taurus 2018 - 2013; Police Sedan 2019 - 2013, Police Interceptor Utility 2015 - 2013; Lincoln Mark LT 2014 - 2010, MKT 2019 - 2013

UNIT PACKAGE: 50



25090
(Ford: W718456-S300)
Black Nylon

Rocker Panel Moulding Clip
Top Head Size: 22mm x 30mm
Overall Height: 18mm
Ford Escape 2020 - On, Explorer 2010 - On; Lincoln Aviator 2020 - On, Continental 2019 - 2017

UNIT PACKAGE: 15



25091
(Ford: W721069-S300)
Yellow Nylon

Liftgate Trim Panel Retainer with Sealer
Top Head Diameter: 16mm
Bottom Head Diameter: 22mm
Stem Diameter: 11mm
Stem Length: 17mm
Ford Bronco 2021 - On

UNIT PACKAGE: 25



25095
(Jeep: 5SR17JXWAA; Fiat: 735537083)
Blue Nylon

Fender & Wheel Moulding Retainer with Sealer
Top Head Size: 12mm sq.
Bottom Head Diameter: 20mm
Stem Size: 8.5mm x 8.5mm
Stem Length: 11mm

Jeep Renegade 2015 - On; Fiat 500 2015 - On

UNIT PACKAGE: 25



25097
(Fiat: 68080648AA)
White Nylon

Rocker Moulding Screw Grommet
Screw Size: M5
Head Diameter: 26mm
Stem Length: 12mm
Overall Height: 27mm
Fits into 8mm x 12.5mm Hole
Fiat 500 2018 - 2012

UNIT PACKAGE: 25



25092
(Infiniti & Nissan: 01241-01051)
Black Nylon & Black Metal Nut



License Plate Bracket U-Nut with Encapsulated Hex Nut
Screw Size: M6-1.0
Width: 16mm
Length: 28mm
Panel Range: 3.5mm

Center of Hole To Edge: 13.5mm
Infiniti G35 2007 - 2004, G37 2013 - 2009, M35, M45 2009 - 2006, Q60 2015 - 2014, Q70 2019 - 2014, QX50 2017 - On, QX80 2019 - 2017
Nissan 350Z 2009 - 2003; 370Z 2009 - On, Armada 2017 - On, Cube 2014 - 2009, Frontier 2019 - 2013, Leaf 2017 - 2011, Pathfinder 1999 - 1996, Rouge 2013 - 2009, Sentra 2018 - 2013, Versa 2019 - 2007

UNIT PACKAGE: 25

Items Available for Immediate Shipment

Photos Actual Size

BMW Clips



25093

(BMW: 51-71-8-234-698)
Black & White Nylon

Cowl Grille Clip with Sealer
Top Head Diameter: 12mm
Middle Head Diameter: 14mm
Bottom Head Diameter: 12.5mm
Stem Diameter: 7.5mm x 9mm
Stem Length: 14.7mm
Overall Height: 20mm
BMW 323, 328 2000 - 1999, 325, 330, M3 2006
- 2001, X3 2017 - 2011, X4 2018 - 2015

UNIT PACKAGE: 25



25094

(BMW: 07-14-7-236-400)
Black Nylon

Liftgate Trim Clip
Top Head Diameter: 16mm
Bottom Head Diameter: 12mm
Stem Diameter: 8mm
Stem Length: 10.5mm
Fits into 8mm Hole
BMW X3 2019 - 2018, X4 2019 - On

UNIT PACKAGE: 25

Repair Harness Connectors




25157

Fog Light Repair Harness
Connector
For 880, 884, 885, 890, 892, 893,
899 Halogen Bulbs
2-18 ga. 11" Leads
Universal

UNIT PACKAGE: 1

WARNING: Cancer and Reproductive Harm -
www.P65Warnings.ca.gov



25159

Headlight Repair Harness
Connector
For H9 Halogen Bulb
2-18 ga. 11" Leads
Universal

UNIT PACKAGE: 1

WARNING: Cancer and Reproductive Harm -
www.P65Warnings.ca.gov



25158

Headlight, Fog Light & Driving
Light Repair Harness Connector
For H8, H11, H12, H16, 862, 881,
886, 889, 894, 896, 898
Halogen Bulbs
2-18 ga. 11" Leads
Universal

UNIT PACKAGE: 1

WARNING: Cancer and Reproductive Harm -
www.P65Warnings.ca.gov



25160

(Ford: CU2Z-14S411-UA;
Motorcraft: WPT-1277;
Toyota: 90980-11875 - Connector
Only)


Variable Timing Solenoid, Fuel
Injector, Knock Sensor Repair
Harness Connector
2-18 ga. 8" Leads

Acura 2017- 2005; Chevrolet Prism 2002 - 1998; Ford;
Lincoln 2017 - 2011; Honda 2016 -2005; Isuzu 2017 - 2004;
Mercedes E-320 2000; Pontiac Vibe 2010 - 2003; Scion
2015 - 2008; Suzuki 2013 - 2009; Toyota 2017 - 1998

UNIT PACKAGE: 1

WARNING: Cancer and Reproductive Harm -
www.P65Warnings.ca.gov

Repair Harness Connectors



25161

Coolant Temp Sensor Repair
Harness Connector
2-18 ga. 8" Leads
Chrysler; Dodge Eagle 2005 -
1993; Hyundai 2011 - 1999; Kia
2013 - 2001; Mitsubishi 2012 -
1993

UNIT PACKAGE: 1

 **WARNING:** Cancer and Reproductive Harm -
www.P65Warnings.ca.gov



25162

MAP, Fuel Vapor, Pressure,
Crankshaft, TPS Sensor, Ignition
Coil Repair Harness Connector
2-18 ga. 8" Leads
Chevrolet Tracker 2004 - 1999;
Infiniti 2019-1990; Isuzu Rodeo
2004; Kia Sephia 1997; Mazda
2015 - 1997; Mercury Villager 2002
- 1996; Mitsubishi 2008 - 2004;
Nissan 2020 - 1989; Subaru 2004
- 1998; Suzuki 2012 - 1998; Toyota
1984 - 1983

UNIT PACKAGE: 1

 **WARNING:** Cancer and Reproductive Harm -
www.P65Warnings.ca.gov